



## Quality Control Chart

Flow	Job Responsibilities		Representative	Affirmant
order review	feasible analysis of manufacturer measurement ability analysis ,delivery date and consignment methods analysis		PE	Business Manager
early plan	APQP/early quality plan of products		multifunctional team	Engineering Supervisor
IQC	Adopt MIL-STD-1050E II AQL0.65		IQC	QA Supervisor
IPQC	Adopt	1,First Article Assurance 2,Period Inspection and use SPC for statistical control 3,Quality abnormal handling	IPQC	IPQC Leader
FQC	Inspect all dimensions according to Drawings		FQC	FQC Leader
OQC	1,Drawings 2,Special Characteristic		OQC	QA Supervisor

Approval: Xiefeng

Check: Zhou Haitian

Prepare: Zhen Xinling